

# General Environmental Incident Summary

**Incident:** 3407      **Date/Time Notice:** 8/1/2014      1341      **DEM Incident No:**

**Responsible Party:** Minnesota Power

**Date Incident:** 7/30/2014      **Time Incident:** 17:00      **Duration:**

**County:** Morton      **Twp:** 140      **Rng:** 85      **Sec:** 4      **Qtr:**

**Lat:** 46.97602      **Long:** -101.42260      **Method:** Interpolation from map

**Location Description:** A spill occurred on the road to the Minnesota Power Bison Facility at 5198 30th Street, New Salem, ND.

**Submitted By:** Greg Prom

**Affiliation:**

**Address:** 30 West Superior Street

**City:** Duluth

**State:** MN

**Zip:** 55802

**Received By:**

**Contact Person:** Todd Simons  
5198 30th Street  
New Salem, ND 58563

**Distance Nearest Occupied Building:**

**Release Contained:** Yes

**Type of Incident:** Hydraulic hose leak

**Description of Released Contaminant:** Hydraulic Oil

**Volume Spilled:** 2.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** No

**Cause of Incident:**

A leak in a hydraulic hose caused a minor leak to the dirt road surface

**Risk Evaluation:**

None

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

Minimal given the spill was to soil, was immediately contained and cleaned up.

**Action Taken or Planned:**

The stained soil on the road was removed and placed in a dumpster for disposal

**Wastes Disposal Location:** Clean Harbors Industrial Solid Waste Landfill in Sawyer, ND

**Agencies Involved:**

## ***Updates***

---

***Date:*** 8/2/2014     ***Status:*** Reviewed - No Action Required

***Author:*** Roberts, Kris

***Updated Volume:***

***Notes:***

Hydraulic hose leak to a road surface. Leak was contained and impact removed according to the report. No follow-up inspection is necessary.